

September 11, 2005

J-31

We landed in Ponca City sometime after 5 pm. We flew over the site but it was raining.

Instrument Status:

RSP all OK except some troubles with maintaining cooling
AATS-14 OK, except freezing of elevation bearing after flying at -21C for extended time. We are positive that with more bearing purge this problem will go away.

Saw Cessna 206 is in Ponca hangar

More updates after 7pm meeting at Ponca Airport.